


HCR335 UM USB Driver Installation Guide

Version:A Date:2011/12

- Power on computer which you will connect the USB devices and make sure that the USB port is enabled and working properly
- Plug in the USB device signal cable into the USB port and Windows will detect an USB Device and run the “**Found New Hardware Wizard**” (For Windows 2000 / XP) or “**Add New Hardware Wizard**” (For Windows 98) to assist you in setting up the new USB Composite Device
- Select “Install from a list or specific location (Advanced)”




- Click “Next”
- Specify the location of USB driver.




- Click Next.

At the time of this product's release, Microsoft strongly encouraged companies to submit their hardware solutions for certification. If a hardware device driver is not submitted, or does not qualify, for Microsoft certification, a warning message appears. You may see this warning message when installing this driver or update. If you do, you may choose to click the Continue Anyway button. We have tested this driver or update on Windows XP, and it does not impair or destabilize your computer.



- Click "Continue Anyway"
- Windows will detect a new USB device (HCR331 Hybrid Card Reader)



- If no any virtual COM port is assigned to this device, you may need to re-install the driver.