


HCR335 VM USB Driver Installation Guide

Version: A Date: 2011/12


- Power on computer which you will connect the USB devices and make sure that the USB port is enabled and working properly
- Plug in the USB device signal cable into the USB port and Windows will detect an USB Device and run the “**Found New Hardware Wizard**” (For Windows 2000 / XP) or “**Add New Hardware Wizard**” (For Windows 98) to assist you in setting up the new USB Composite Device
- Select “Install from a list or specific location (Advanced)”




- Click “Next”
- Specify the location of USB driver.



- Click Next.
- Click “Finish”



- Windows will detect a new USB device (HCR335)



- If no any virtual COM port is assigned to this device, you may need to install the driver again.